



AERO CAPITAL S.A.S

1, rue de Stockholm
75008 Paris
FRANCE

Tel : (00 33) 1.44.707.214
Fax : (00 33) 1.44.707.216
Mail : contact@aero-capital.com

- 1981 –DASSAULT FALCON 20F-5BR –



AIRFRAME

DFS MAINTENANCE CONTRACT
10.107 time since new
7.179 landings

ENGINES

TFE 731-5BR-2C – MSP
Left Right
6.026 TSN 6.142 TSN

APU

GARRETT GTCP 36-150W

AVIONICS

AP/FD	COLLINS AP 105
VHF (DUAL)	COLLINS 22B
VOR (DUAL)	COLLINS VIR 32
DME (DUAL)	COLLINS DME 42
ADF (DUAL)	COLLINS ADF 60
XPNDR (DUAL)	COLLINS TDR 90
RADAR	SPERRY PRIMUS 400
RADAL	COLLINS ALT 50A
HF COM	COLLINS
IFS (DUAL)	COLLINS FD 109
RMI (DUAL)	COLLINS RMI 30
FMS/GPS (DUAL)	GLOBAL GNS-XLS
CVR	FAIRCHILD A100

INTERIOR (NEW 1999)

- 9 pax +1 certified jumpseat –Light beige leather – Beige carpet – Aft club seat opposite to a 3 place sofa – 4 fwd club seats –Aft lav –
- 3 executive folding tables - Laminate wood cabinets with Australian red gum wood veneer – Fwd galley with coffee maker and microwave -

EXTERIOR (NEW 2008)

- Silver with black and red stripes -

MISCELLANEOUS

- RVSM Certified – AFIS - Heads-up technologies talking checklist - EROS oxygen masks - Cabin Flood Duct System –
- 4C and MCI inspection completed 5/2005 – Z inspection 6/2007 – Gear overhaul 8/1998 -
- Auto flight 2 passenger briefing system -Dual Davtron clocks - Lead Acid batteries - Forward battery relocation - JET Emergency Power Supply -
- Falcon 200 Tail Cone – Hoskins Twiligher 3 Strobe System - Eldec Fuel Flow Monitoring System - SB 701 completed - Duncan Aft Baggage Mod -

- Specifications subject to verification upon inspection – Availability to prior sale – 02/10