



1989 Hawker 125-800A S/N 258153 Reg: HB-VHV



Technical Specifications - Pictures

Airframe

10,659 Time since new

8,115 Cycles since new

Engines

GRT TFE731-5R-1H

MSP GOLD – SOAP ANALYSIS

Left : 10,205 TSN

Right: 10,303 TSN

APU

TURBOMACH SUNDSTRAND T-62T-40C8D1

On MSP

3,968 TSN

Avionics

AP/FD	COLLINS PROLINE 21IDS
VHF (DUAL)	COLLINS PROLINE
VOR (DUAL)	COLLINS PROLINE
DME (DUAL)	COLLINS DME 42
XPDR (DUAL)	COLLINS TDR 94D S MODE
TCAS II	CAS II
RADAL	COLLINS PROLINE
IFIS	IFIS 5000 SYSTEM
HF (DUAL)	DUAL HF COMM
FMS	UNIVERSAL UNS 1D+
EGPWS	HONEYWELL MARK VII

Exterior

Overall snow white with red and grey stripes on fuselage

Interior

8 pax

Five Single Chair

One three seat divan

Fwd LH Galley

Toilet external serviceable

Micro Wave Oven -

Satcom Handset at LH VIP seat

115 VAC Inverter / Outlet

Jump Seat and Cabin Attendant PBE

Miscellaneous

FAA / EU OPS1 Compliant

RVSM

B-RNAV

IFR CAT II

XM-Weather provision

AirCell Iridium ST3100 Satcom installation Securaplane Emergency

Batteries installation

Logo lights

Lead Acid Main Batteries

Pulse Light System

Doors equipped with “Medeco” lock system

Nose and Main Landing Gear overhauled (July 2009) LH & RH

Starter Generator overhauled (July 2009)

24/48/96/144 month Structural due items inspection and x-ray (July 2009)

No history damage

All logs

Specifications are Subject to Verification Upon Inspection. Offered Subject to Prior Sale or Withdrawal from Market – 02-2011 -











