



AERO CAPITAL S.A.S

1, rue de Stockholm
75008 Paris
FRANCE

Tel : (00 33) 1.44.707.214
Fax : (00 33) 1.44.707.216
Mail : contact@aero-capital.com

- 1982 – FALCON 50 – S/N 108 – N150K -

AIRFRAME

TSN 9.591
CSN 5.515



ENGINES

ALLIED SIGNAL TFE 731-3-1C – ON MSP

Engine # 1
TSN: 3.677

Engine # 2
TSN: 3.732

Engine # 3
TSN: 3.732

APU

HONEYWELL GTCP-36-100 - MSP
TSN : 3.176

AVIONICS

FMS (DUAL)	COLLINS FMC 6000
AP/FDS (DUAL)	COLLINS APS 85
VHF (TRIPLE)	COLLINS VHF 422D
VOR (DUAL)	COLLINS VIR 432
DME (DUAL)	COLLINS DME 442
ADF (DUAL)	COLLINS ADF 60A
XPDR (DUAL)	COLLINS TDR 94D
RADAR METEO	COLLINS RTA 858
RADAL	COLLINS ALT 55B
TCAS	HONEYWELL TTR 4000 CH 7
HF (DUAL)	COLLINS HF W/ SELCAL
CVR	FAIRCHILD GA100
EGPWS	HONEYWELL

INTERIOR (2001)

- 12 pax – 4 Club seats fwd and 2 aft facing club seats– Aft 3 place divan – Light Beige leather seats and carpet – Matte woodwork finish – Aft lavatory -

EXTERIOR (2002)

- White with tan and blue accent stripes -

MISCELLANEOUS

- RVSM – BRNAV – Dual Channel Flight Phone - Tri band ELT – Cabin Display - No Damage History -

- Specifications subject to verification upon inspection - Availability to prior sale – 06/08 -